PT-056: Underwater Case System Chart

Electronic Flash
UFL-1
- Withstand pressure water depth: 40 m



Weight
PWT-1AD

Weight
PWT-1BA

Underwater optical fiber cable
PTCB-E02

Optical Cable Adapter
PFCA-02
(provided with the PT-056)

Electronic Flash
UFL-2
- Withstand pressure water depth: 60 m

Diffuser for UFL-2
UFLDP-3

Short Arm
PTSA-02

Short Arm
PTSA-03

Waterproof Compact Cameras
TOUGH TG-3
RED

Waterproof Compact Cameras
TOUGH TG-3
BLACK

Antireflective Ring
POSR-053
(provided with the PT-056)

Underwater Case for TOUGH TG-3
PT-056

LCD hood
PFUD-08
(provided with the PT-056)

Step-up Ring
PSUR-03
- ø52mm-67mm

Lens Cap
PRLC-14
(provided with the PT-056)

Underwater approx. 0.6X (underwater angle of view approx. 100°)

Underwater Wide Conversion Lens
PTWC-01
- Change the digital camera setting. Press the MENU button, then select "PTWC-01" under "Accessories" in the "Shooting menu 2". Then press the OK button.
- Even if the setting has been changed, the four corners of the image may be darkened when the zoom is used.
- When used on land, the four corners of the image get cropped.

Underwater approx. 2X (area ratio)

Underwater Macro Conversion Lens
PTMC-01
- The tip is provided with a 67 mm diameter filter thread for stacking with other lens filter or lens.

Hand strap
PST-EP01
RED

Consumables for PT-056 Underwater Cases

Silicone grease
PSOLG-2
(5 g)

Silicone grease
PSOLG-3
(40 g)

Silica gel
SILCA-5S
(1 g x 5 pieces)

O-ring for PT-056
POL-053

Maintenance Set
PMS-02